

Generic Task/ Person Based Risk Assessment	Reference:
Operational and Non-operational response to COVID-19 pandemic	GRA COVID-19 V3
For staff working in NIE Networks controlled locations including offices, stores and work sites. To be	Review Date:
used with COVID-19 Risk Assessments for offices & craft specific WIRA	10/06/2021

	At Risk - E - Employee, C - Contractor, P - Public Initial Risk - C - Consequence, L - Likelihood										
Hazard & Sub Category	At Risk -	ı	nitial R	isk	Control Measures	Res	sidual	Risk			
	E, C or P	С	L	Risk	Control Measures	С	L	Risk			
Spread of COVID-19	E,C&P	5	5	2 5	Consult and apply Government guidance	5	1	5			
Policy & Guidance					Consult and apply HSENI guidance						
					British Red Cross First Aid Advice						
					Public Health Agency (PHA) General Advice Relating to COVID-19						
					Consult and apply company guidance:						
					- COVID-19 Precautions for Working <2 Metre Seperation						
					- HSG-030 Entering Customer Premises During COVID-19 Pandemic						
					- Guidelines for Essential - Non-Essential Work During the COVID-19 Period &						
					associated Addendums						
					- COVID-19: Employee Roster Rquirements						
					- COVID-19 Authorisation Letter						
					- COVID-19 Pandemic - Face Coverings						
					- Coronavirus 'Frequently Asked Questions'						
					- Working From Home Guidlines						
					- Self-isolation checklist						
					- Minding Your Mental Health						
					- COVID-19 Risk Assessment for Offices						
					- WJRA COVID-19 Entering Customer Premises and Where 2 Metres Social						
					Distancing Cannot Be Maintained						
					- COVID-19 Advice re. Meeting and Events						
					- Tool Box Talk No. 108 - Cleaning of Vehicle Interiors to Reduce the Risk of						
					Spreading Coronavirus.						



Generic Task/ Person Based Risk Assessment	Reference:
Operational and Non-operational response to COVID-19 pandemic	GRA COVID-19 V3
For staff working in NIE Networks controlled locations including offices, stores and work sites. To be	Review Date:
used with COVID-19 Risk Assessments for offices & craft specific WJRA.	10/06/2021

	At Risk -	Initial Risk			2	Residual Risk				
Hazard & Sub Category E,	E, C or P	С	L	Risk	Control Measures	С	L	Risk		
Sub Category										
All staff - Spread of COVID-19 - Symptoms of COVID-19 & Company Updates	E&P	5	4	20	 If you have any of the symptoms of coronavirus or if you're identifed as a close contact, you should behave as if you have the virus, self-isolate for 10 days, call your GP and get tested. If you test positive for coronavirus, contact your Line Manager and follow governement guidelines. If 'High Risk' Letter received from government, follow advise and inform the Company and your Line-Manager. Self-isolate for 10 days if you have returned from foreign travel. All staff to receive specific COVID-19 back-to-work interview. At all stages keep the Company and your Line Manager updated. 	5	1	5		
All staff - Social Distancing	E,C&P	5	4	20	 Access to all sites controlled to prevent unnecessary access Only essential vistors permitted Use of passenger lifts restricted: 1 person per lift. Staff to work in dedicated teams and avoid rotation where practicable Keep a social distance of 2 metres (6.5 feet). Reduce physical interactions with people. Reduce the number of people you meet every day. Avoid crowded places, especially indoors. Do not shake hands and where practicable do not make close contact with others. Office staff rostered and working from home on alternate days. Support staff with Display Screen Equipment (DSE) requirements. 	5	1	5		



Generic Task/ Person Based Risk Assessment	Reference:
Operational and Non-operational response to COVID-19 pandemic	GRA COVID-19 V3
For staff working in NIE Networks controlled locations including offices, stores and work sites. To be	Review Date:
used with COVID-19 Risk Assessments for offices & craft specific WIRA	10/06/2021

Harand & Cub Catarray	At Risk -	Initial Risk			0	Residual Risk				
Hazard & Sub Category	E, C or P	С	L	Risk	Control Measures	С	L	Risk		
All staff -	E,C&P	5	4	2 0	Everyone has a personal responsibility to cooperate with location landlords	5	1	5		
Personal Hygiene					and other employees and to ensure their own behaviours limit the potential					
					spread of Covid-19					
					Wash hands regularly and/ or hand sanitiser applied.					
					Cover your mouth and nose with a tissue or your sleeve when you cough and					
					sneeze.					
					Face coverings and disposal nitrile gloves available for all staff and must be					
					worn when working within 2m.					
					Staff encouraged to wear face coverings when moving around the office.					
					Put used tissues into a bin and wash your hands.					
					Clean and disinfect frequently touched objects and surfaces.					
					Avoid touching your eyes, nose or mouth, especially if your hands are not					
					clean.					
					• The allocation of other workstations in offices may require an element of desk					
					sharing, however this should be avoided where practicable.					
					Do not share objects that touch your mouth, e.g. bottles, cups.					
All staff -	E,C&P	5	4	2 0	Limit/ avoid the use of public transport	5	1	5		
Travel					Avoid sharing vehicles. If required to do so, follow all issued guidance.					
					Shared vehicles must be cleaned before and after use, good ventilation					
					maintained. Face coverings to be worn.					
					Maximum of 2 passengers per vehicle					
					Avoid non-essential travel, including overseas, and follow the Government's					
					travel advice.					



Generic Task/ Person Based Risk Assessment	Reference:
Operational and Non-operational response to COVID-19 pandemic	GRA COVID-19 V3
For staff working in NIE Networks controlled locations including offices, stores and work sites. To be	Review Date:
used with COVID-19 Risk Assessments for offices & craft specific WJRA.	10/06/2021

Hazard & Sub Category	At Risk -	Initial Risk			Control Massives	Residual Risk			
Hazaru & Sub Category	E, C or P	С	L	Risk	Control Measures	С	L	Risl	
All staff -	E&C	4	3	<u>12</u>	Promote mental health & wellbeing awareness to staff.	5	1	O 5	
Mental Health					Line Managers to maintain frequent communication with staff, providing				
					updates on company's approach and checking on staff's wellbeing.				
					Professional welfare provision provided by Clarity Associates.				
Office based staff -	E,C&P	5	2	0 10	Where practicable staff maintain normal business operations by working	5	1	<u> </u>	
Where remote access is					remotely from home.				
available and tasks can be					Where practicable use teleconferencing facilities for meetings.				
completed remotely.					DSE remote working advice issued to staff				
Office based staff -	E,C&P	5	3	1 5	• Site specific COVID-19 Risk Assessment completed and control measures	5	1	5	
Where remote access is not					applied.				
available and tasks cannot					Landlord or appointed deputy on-site during working week to monitor				
be completed remotely.					controls and apply additional control measures as necessary.				
					• Office based staff should attend the office/depot in agreement with their Line-				
					Manager and inline with Company guidance.				
Toom Managars 9 Lina	E,C&P	5	3	1 5	Work to be carried out inline with company guidance.	5	1	<u> </u>	
Team Managers & Line-					Consider social distancing and company guidance when planning/ scheduling				
Managers of front-line staff					work.				
Team Managers & Line-	E,C&P	5	2	0 10	Office staff rostered and working from home on alternate days.	5	1	<u> </u>	
Managers of front-line staff	_				Use teleconference for any planned group meetings where possible &				
Where remote access is					practical.				
available and tasks can be					Issue work electronically.				
completed remotely.					·				



Generic Task/ Person Based Risk Assessment	Reference:
Operational and Non-operational response to COVID-19 pandemic	GRA COVID-19 V3
For staff working in NIE Networks controlled locations including offices, stores and work sites. To be	Review Date:
used with COVID-19 Risk Assessments for offices & craft specific WIRA.	10/06/2021

	At Risk -	Ir	nitial Ri	sk		Residual Risk				
Hazard & Sub Category	E, C or P	С	L	Risk	Control Measures	С	L	Risk		
Team Managers & Line- Managers of front-line staff Where remote access is not available or tasks cannot be completed remotely.	E,C&P	5	3	15	 Ensure 2m social distancing when planning and issuing work. Staff should attend the office/depot in agreement with their Line-Manager and inline with Company guidance. 	5	1	5		
Operational Engineers/ Technicians	E,C&P	5	3	1 5	 Only work to be carried out inline with company guidance. Consider social distancing and company guidance when planning work. 	5	1	<u> </u>		
Operational Engineers/ Technicians - Where tasks can be completed remotely from home.	E,C&P	5	2	10	Where practicable office based operational duties must be carried out remotely from home. Use teleconference facilities for any planned group meetings where possible & practical.	5	1	5		
Operational Engineers/ Technicians - Where tasks cannot be completed remotely from home.	E,C&P	5	3	15	 Where practicable maintain 2m social distancing when providing supervision, issuing instructions, Safety Documents, etc. Staff should attend the office/depot in agreement with their Line-Manager and inline with Company guidance. Where it is not possible to maintain the social distance of 2m for essential activities the 'WJRA COVID-19 Entering Customer Premises and Where 2 Metres Social Distancing Cannot Be Maintained' must be completed and control measures applied. Sign documents using personally held pens. PPE - Visor, face coverings and disposal nitrile gloves must be worn when working within 2m. 	5	1	5		



Generic Task/ Person Based Risk Assessment	Reference:
Operational and Non-operational response to COVID-19 pandemic	GRA COVID-19 V3
For staff working in NIE Networks controlled locations including offices, stores and work sites. To be	Review Date:
used with COVID-19 Risk Assessments for offices & craft specific WIRA	10/06/2021

Lloroud & Cub Cotorous	At Risk -	Risk - Initial		isk	0	Residual Risk			
Hazard & Sub Category	E, C or P	С	L	Risk	Control Measures	С	L	Risk	
Field staff -	E,C&P	5	4	2 0	Report to work as directed by your Team Manager.	5	1	5	
Social Distancing & Team					Where practicable receive work remotely and report directly to site.				
Manager Updates					Do not report to an office or depot unless directed by your Team Manager.				
					• Consider social distancing and company guidance when planning and carrying out work.				
					• Only congregate for essential activities (e.g. WJRA sharing, Safety Document and Work Instruction issue and cancellation, etc.).				
					Where it is not possible to maintain the social distance of 2m for activities the				
					'WJRA COVID-19 Entering Customer Premises and/or Where 2 Metres Social				
					Distancing Cannot Be Maintained' must be completed and control measures applied.				
					 Where deemed necessary Designated Observer appointed to ensure 2m social 				
					distancing is maintained.				
					Sign documents using personally held pens.				
					Avoid mixing teams where reasonably practicable.				
					Stagger break times to maintain 2m social distancing.				
					Maximum of 2 passengers per vehicle				
					• When entering/ working in a customer's property control measures detailed in				
					HSG-030 'Entering Customer Premises During COVID-19 Pandemic' must be				
					observed.				



Generic Task/ Person Based Risk Assessment	Reference:			
Operational and Non-operational response to COVID-19 pandemic	GRA COVID-19 V3			
For staff working in NIE Networks controlled locations including offices, stores and work sites. To be	Review Date:			
used with COVID-19 Risk Assessments for offices & craft specific WIRA	10/06/2021			

Hazard & Sub Category	At Risk -	Initial Risk			Control Measures	Residual Risk				
	E, C or P	C L Risk		С	L	Risk				
Field staff - Personal Hygiene	E,C&P	5	4	20	 Where reasonably practicable avoid sharing tools without suitable cleaning. When a work vehicle is shared ensure all areas liable to be touched (including keys of vehicle) are suitably cleaned on entering and exiting the vehicle. Maintain good ventilation ensuring the air in the cab is suitably circulated. PPE - Visor, face coverings and disposal nitrile gloves must be worn when working within 2m. 	5	1	5		
Supply Chain & Stores Staff	E,C&P	5	3	15	 Report to stores/ depot as directed my Team Manager. Where it is not possible to maintain the social distance of 2m for essential activities the 'WJRA COVID-19 Entering Customer Premises and/or Where 2 Metres Social Distancing Cannot Be Maintained' must be completed and control measures applied. PPE - Visor, face coverings and disposal nitrile gloves must be worn when working within 2m. 	5	1	5		

The control measures are to reduce the likelihood of contracting COVID-19 to as low as reasonable practicable.

The consquence will remain high as there is no control measures identified that will reduce the contracted strength of COVID-19.

On-site WJRA must be completed for all work related tasks and will include COVID-19 control measures.